

xBolt

Pre-Run Preparations

EXTREME™



Objectives

- Learn how to assemble all xBolt tool string
- Know how to strap xBolt equipment for run
- Setup surface software for job
- Understand how to program and test tools
- Finalize equipment setup to pick up for run

xBolt Pre-Run Preparations

Probe Assembly Order


Probe Assembly Order – R Dual Telemetry – Extreme Probes

7 Main Components

- R-Fishing Head (XET)
- Battery Probe(s) (DOBA)
- D&I Probe (SOCD)
- Gamma Probe (XGM)
- Dual Telemetry Probe (XDT)
- Gap Probe (XGP)
- xBolt-R Pulsar (XPR)

■ Sub Components

- Bowsprings
- Field Resizable Centralizers
- Connector Housing



***Build tool from Pulsar on**

****DOBA, SOCD and XGM may be placed in any order above XDT**

Never connect battery probes to XDT prior to assembly of XGP and Pulsar to XDT.


Probe Assembly Order – R Mud Pulse Only – Extreme Probes

6 Main Components

- R-Fishing Head (XET)
- Battery Probe(s) (DOBA)
- D&I Probe (SOCD)
- Gamma Probe (XGM)
- Dual Telemetry Probe (XDT)
- xBolt-R Pulser (XPR)

■ Sub Components

- Field Resizable Centralizers



***Build tool from XPR upward**

****DOBA, SOCD and XGM may be placed in any order above XDT**

Never connect battery probes to XDT prior to assembly of Pulser to XDT.

Probe Assembly Order – L Dual Telemetry – Extreme Probes

8 Main Components


- L-Pulser (MOP)
- MOP Interface Probe (XIPL)
- Gap Probe (XGP)
- Dual Telemetry Probe (XDT)
- D&I Probe (SOCD)
- Battery Probe(s) (DOBA)
- Gamma Probe (XGM)
- Extreme End Stabilizer (ENDS)

***Build tool from MOP downward**

****DOBA, SOCD and XGM may be placed in any order below XDT**

■ Sub Components

- Bowsprings
- Field Resizable Centralizers



Never connect battery probes to XDT prior to assembly of XGP and MOP to XDT.


Probe Assembly Order – L Mud Pulse Only – Extreme Probes

7 Main Components

- L-Pulser (MOP)
- MOP Interface Probe (XIPL)
- Dual Telemetry Probe (XDT)
- D&I Probe (SOCD)
- Battery Probe(s) (DOBA)
- Gamma Probe (XGM)
- Extreme End Stabilizer (ENDS)

■ Sub Components

- Field Resizable Centralizers



***Build tool from MOP downward**

****DOBA, SOCD and XGM may be placed in any order below XDT**

Never connect battery probes to XDT prior to assembly of MOP to XDT.

Probe Assembly Order – EM Only – Extreme Probes

6 Main Components


- Gap Probe (XGP)
- Dual Telemetry Probe (XDT)
- Battery Probe(s) (DOBA)
- D&I Probe (SOCD)
- Gamma Probe (XGM)
- Extreme End Stabilizer (ENDS)

***Build tool from XGP downward**

****DOBA, SOCD and XGM may be placed in any order below XDT**

■ Sub Components

- EM Fishing Head
- Bowsprings
- Field Resizable Centralizers



Never connect battery probes to XDT prior to assembly of XGP to XDT.

Probe Assembly Order – R Dual Telemetry – xBolt Probes

6 Main Components


- R-Fishing Head (XET)
- Azi Gamma/D&I Probe (XDAG)
- Battery Probe(s) (XBAT)
- Dual Telemetry Probe (XDT)
- Gap Probe (XGP)
- xBolt-R Pulser (XPR)

***Build tool from XPR upward**

****XBAT and XDAG can be in any order above XDT**

■ Sub Components

- Bowsprings
- Field Resizable Centralizers
- Connector Housing



Never connect battery probes to XDT prior to assembly of XGP and Pulser to XDT.

Probe Assembly Order – R Mud Pulse Only – xBolt Probes

5 Main Components


- R-Fishing Head (XET)
- Azi Gamma/D&I Probe (XDAG)
- Battery Probe(s) (XBAT)
- Dual Telemetry Probe (XDT)
- xBolt-R Pulser (XPR)

***Build tool from XPR upward**

****XBAT and XDAG can be in any order above XDT**

■ Sub Components

- Field Resizable Centralizers



Never connect battery probes to XDT prior to assembly of Pulser to XDT.


Probe Assembly Order – L Dual Telemetry– xBolt Probes

7 Main Components

- L-Pulser (MOP)
- MOP Interface Probe (XIPL)
- Gap Probe (XGP)
- Dual Telemetry Probe (XDT)
- Battery Probe(s) (XBAT)
- Azi Gamma/D&I Probe (XDAG)
- End Terminator (XETL)

■ Sub Components

- Bowsprings
- Field Resizable Centralizers



***Build tool from MOP Downward**

****XBAT and XDAG can be in any order below XDT**

Never connect battery probes to XDT prior to assembly of XGP and MOP to XDT.

Probe Assembly Order – L Mud Pulse Only – xBolt Probes

6 Main Components


- L-Pulser (MOP)
- MOP Interface Probe (XIPL)
- Dual Telemetry Probe (XDT)
- Battery Probe(s) (XBAT)
- Azi Gamma/D&I Probe (XDAG)
- End Terminator (XETL)

***Build tool from MOP
Downward**

****XBAT and XDAG can be in
any order below XDT**

■ Sub Components

- Field Resizable Centralizers



*Never connect battery probes to XDT
prior to assembly of MOP to XDT.*

Probe Assembly Order – EM Only – Extreme Probes

5 Main Components


- Gap Probe (XGP)
- Dual Telemetry Probe (XDT)
- Battery Probe(s) (XBAT)
- Azi Gamma/D&I Probe (XDAG)
- End Terminator (XETL)

***Build tool from XGP downward**

****XBAT and XDAG can be in any order below XDT**

■ Sub Components

- EM Fishing Head
- Bowsprings
- Field Resizable Centralizers





Never connect battery probes to XDT prior to assembly of XGP to XDT.

xBolt Tool Pre-Run Preparations

Building the Tool

Building the Tool – Pre-Assembly Checks

- Verify centralizers are sized for BHA and can drift all IDs in BHA where tool is housed
 - 2 11/16” – 475 BHA
 - 3 1/4” – 675 BHA
 - 3 1/2” – 800 BHA
- Inspect each connector for damage, clean with contact cleaner if necessary
- Inspect O-Rings for damage, apply DC111 to O-Rings
- Verify all three sizes of torque wrenches are available in kit: 1.75”, 1.875”, 2.00”
- Verify bow spring is installed is proper size and placement for tool string and BHA



Building the Tool – Golden Rule Assembly

Never connect battery probes to XDT prior to assembly of XGP and Pulser to XDT. Failure to do so could lead to current spike through XDT which will damage electronics.

Building the Tool – Assembly HSE

- Always wear steel toed boots, hard hat, safety glass, FR clothing and metatarsal gloves during assembly
- Use proper SIPP during all assembly operations
- LF MOP, XDAG and XBAT exceed 50lbs, use two man lift if unable to carry probe
- Never jump on barrel wrenches



Building the Tool – Assembly Steps

- Step 1: Lay out tool string on jack stands in order
- Step 2: Begin assembling string from pulser downwards (upwards for xBolt-R), assemble all connections by hand before torqueing with barrel wrenches
- Step 3: Mark each connection with paint pen prior to torqueing
- Step 4: Communicate with tool string prior to applying torque and verify all nodes are present
- Step 5*: Begin torqueing string to 350 ft/lbs with barrel wrenches in same order as string was assembled. Be sure to verify torque on all field replaceable centralizers.
- Step 6: Verify all paint pen marks show torque applied

***DO NOT TORQUE ACROSS XEM PROBES CENTRALIZERS.**




Building the Tool – Barrel Wrench Size Guidelines

- 2.00" Barrel wrench used for:
 - XDT
 - XDAG
 - XGP
- 1.875" Barrel wrench used for:
 - Field Resizable Centralizers
 - XETL
 - XBAT
- 1.75" Barrel wrench used for:
 - All XEM Probes
 - EM Fishing Head
 - R-Fishing Head



Building the Tool – Post Assembly Cleanup

- Once the tool string is assembled, collect the dust caps and store them in kit to prevent debris entering dust caps
- Return barrel wrenches and excess jack stands to kit box to prevent rusting



xBolt Tool Pre-Run Preparations

Strapping MWD Iron


Strapping MWD Iron – Strapping HSE

- Always wear steel toed boots, hard hat, safety glass, FR clothing and metatarsal gloves during strapping
- In low light condition, bring flashlight to identify hazards
- Never stick your hand inside a sub or collar before looking inside of it
- Never stand between two collars on a rack





Strapping MWD Iron – Strapping Muleshoe Sub – xBolt-R

- Measure overall length of muleshoe sub from box seal face to pin seal face (L1)
- Measure distance from center of set screw hole to pin seal face (L2)
- Measure OD of sub near top of sub
- Measure ID of sub
- Record serial number of sub
- Draw fishing diagram with all information




Strapping MWD Iron – Strapping Pulser Sub – xBolt-L

- Measure overall length of pulser sub from box seal face to pin seal face (L1)
- Measure distance from bottom of recess to pin seal face (L2)
- Measure sub internal bore depth (A)
- Measure OD of sub near top of sub
- Measure ID of sub
- Record serial number of sub
- Draw fishing diagram with all information



Strapping MWD Iron – Strapping Gap Sub – xBolt DT or EM

- Measure overall length of gap sub from box seal face to pin seal face (L1)
- Measure distance from center of set ground plug hole to pin seal face (L2)
- Measure OD of sub near top of sub and below gap
- Measure ID of sub
- Record serial number of sub
- Draw fishing diagram with all information




Strapping MWD Iron – Strapping NMDCs, NMFCs and NMPCs

- Measure overall length of collar(s) from box seal face to pin seal face
- Measure OD near top of collar(s)
- Measure ID of collar(s)
- Record serial number of collar(s)
- If using flex collars or ponies, strap distance to all upsets and record OD of each section
- Once offsets have been calculated for the run, measure OD of approximate area gamma sensor will sit
- Draw fishing diagram with all information



Strapping MWD Iron – Dual Telemetry Checks – MS Sub and Gap Sub

- Physical gap in gap probe (plastic sleeve) must sit within physical gap of gap sub for EM functionality
- Verify distance (D) between set screw port in muleshoe sub to gap sub ground plug ports falls within allowable range
- Refer to ITC # [7351465](#)



	NEW	RECUT MIN
A	39.00	31.9
B	29.78	27.68
C	9.22	4.22
D	43.28	36.18
O.D.	4.75	4.70

475 Tool

	NEW	RECUT MIN
A	40.0	31.25
B	30.41	27.66
C	9.59	3.59
D	43.29	37.79
O.D.	6.50	6.45


675 Tool

	NEW	RECUT MIN
A	39.00	31.75
B	31.41	28.66
C	7.59	3.09
D	44.86	42.11
O.D.	8.00	7.95

800 Tool

Strapping MWD Iron – Dual Telemetry Checks – Pulser Sub and Gap Sub

- Physical gap in gap probe (plastic sleeve) must sit within physical gap of gap sub for EM functionality
- Verify distance (D) between bottom of recess to gap sub ground plug ports falls within allowable range
- Refer to ITC # [7290551](#)



	NEW	RE CUT- MIN
A	63.6	52.6
B	45.8	38.8
C	16.9	12.9
D	47.7	39.7
O.D.	4.80	4.70

475 Tool

	NEW	RE CUT- MIN
A	70.1	59.1
B	52.2	45.2
C	17.1	13.1
D	47.7	39.7
O.D. 5-1/2 FH	7.00	6.70
O.D. 4-1/2 IF	7.00	6.45

675 Tool

	NEW	RE CUT- MIN
A	70.0	59.0
B	52.2	45.2
C	16.9	12.9
D	47.7	39.7
O.D.	8.125	7.050

800 Tool

xBolt Tool Pre-Run Preparations

Tool Length Calculation

Tool Length Calculation – Tool Length Calculator

- Obtain final BHA from DD and verify iron measurements match MWD strap
- Using measurements obtained from strap, fill out collar lengths and reference point measurements in calculator
- Select appropriate probes and verify they are in order on calculator compared to tool assembly
- Note down offsets in calculator, verify position of gamma sensor in BHA and corresponding OD/ID
- Verify D&I package is not near any wear bands or stabilizer blades as they could be magnetized
- Tool length calculator is located in ITC #[7288212](#)

Inputs:	ft	m
Length of BHA Below Pulser Sub	45	13.72
Bottom of Pulser Sub Ring to Pin of Pulser Sub	1.42	0.43
MWD Collar(s) Length	34.74	10.59
Gap Sub Length	3.68	1.12
Measured Distance from Shoulder (Box) of PowerDrive to Internals	2.79	0.85

Select probe from the drop down menu

Mud Pulse/Dual Telemetry(MOP Always Goes First)		
Mini-MOP	2.60	0.79
L Extender Probe	2.44	0.74
XGP	2.43	0.74
XDT	5.51	1.68
XBAT	8.97	2.73
XDAG	6.21	1.89
L/S End Terminator	0.21	0.06
None	0.00	0.00
None	0.00	0.00
None	0.00	0.00
None	0.00	0.00
None	0.00	0.00
None	0.00	0.00
None	0.00	0.00


XEM D&I to Bit	0.00	0.00
XEM Gamma to Bit	0.00	0.00
XDAG D&I to Bit	26.73	8.15
XDAG Gamma to Bit	23.09	7.04
Tool to Collar Bottom	14.42	4.40
XHOP - POWERDRIVE DISTANCE	0.00	0.00
BABELFISH - POWERDRIVE DISTANCE	0.00	0.00

xBolt Tool Pre-Run Preparations

XDirect Software Setup


Software Setup – Verifying XM4 Connections to Computer

- Open “Device Manager” to verify all necessary connections are showing if using USB connections
 - CAN-Hardware
 - Needed for tool programming
 - Extreme XEM Downlinker
 - Needed for surface and downhole EM downlinks
 - EXTREME XM4 Receiver
- Note down COM Ports
 - In this example, COM12 for Downlinker, COM13 for XM4




Software Setup – Verifying XM4 Connections to Computer

- If using Isolator connection for XM4/Downlinker, one of the “Enhanced” COM Ports will be used for connection
- Downlinker connection will be going through XM4 and can be selected in downlinker application



Software Setup – xDirect Job Setup

- Open “Launcher” to go to landing page
- Select “Tool Setup” icon to begin job setup



The screenshot displays the xDirect software interface. At the top center, there is a dark blue square icon labeled "Launcher" with a green checkmark and a wrench symbol. Below it is a window titled "EXTREME MEASUREMENT WHILE DRILLING". The main area is divided into four columns: "Run Setup", "Drilling and Logging", "Post-Run", and "Reporting".

- Run Setup:** Contains icons for "TOOL SETUP" (wrench) and "LIVE TOOL COMM" (Wi-Fi symbol).
- Drilling and Logging:** Contains icons for "TOOLFACE" (target) and "SURVEY" (globe).
- Post-Run:** Contains an icon for "MEMORY DUMP" (SD card).
- Reporting:** Contains icons for "SIGNAL ANALYSIS" (clipboard) and "INTERACT" (recycling symbol).

At the bottom right, there is a "JOB MENU" section with options: "NEW", "IMPORT", and "EXPORT". To its right, job details are displayed for "19MLD4399 Red Lodge C20 - 11F 6H":


Active Run	: 2
Start Date	: 29-Jul-2019
Current Depth	: 22469ft
File Size	: 838 MB

At the bottom left, there is a section labeled "ACTIVATE RUN FOR REALTIME LOGGING" with a progress bar and the number "2".

Software Setup – xDirect Job Setup

- Select “New Run” or select desired run and click “View/Edit”
- If plugged into correct tool for run selected, click “Update” when prompted.
- If not plugged into a tool or plugged into tool for different run, click “Ignore”

ID	RUN NAME	ACTIVE (REALTIME LOG)	START DATE	END DATE
1	1	No	14:48:28 18-Jul-2019	18:57:43
3	2	Yes	22:34:42 28-Jul-2019	15:18:38





Tools have changed

You may select another Run, retry tool detection or ignore the differences.



Software Setup – XDirect Job Setup

- Go through each tab and fill out all relative information related to job
- FAC criteria will be used in programming for high side




xBolt Tool Pre-Run Preparations

Tool Programming

Tool Programming – Tool Communication

- Verify all nodes appear on right hand side of screen for tool string
- If no nodes showing, click refresh button to request node identification
- If XDT Bank Test is open, communication to tool won't work in XDirect



Tool Nodes

- XDT (String XDT)
 - XDTM
 - XDT Class D
 - DDR
 - PPP
 - Flow Switch
- XDAG
- Battery(s)
 - Battery A (Nearest battery to XDT)
 - Battery B (Second battery from XDT)
 - Battery C (Third battery from XDT)
- SOCD
 - D&I
 - DynamX
- Gamma

Tool Programming – Firmware Update

- Verify firmware up to date on tool string
- Firmware may be upgraded from this page
- Latest firmware may be found on ITC# [7299778](#)


The screenshot displays the 'Firmware Update' window from the 'EXTREME MEASUREMENT WHILE DRILLING' application. The window title bar includes the application name and standard window controls. Below the title bar is a menu bar with 'File', 'Edit', 'View', 'Run', and 'Help'. The main content area is titled 'Firmware Update' and features an 'Estimated time to flash' field set to '00:02:30'. A table titled 'AVAILABLE TOOLS TO UPGRADE FIRMWARE' lists various tools with their upgrade status, preferred version, current version, and result. The table data is as follows:

UPGRADE?	TOOL	PREFERRED	+/-	CURRENT	TIME	RESULT
No	Battery A	2.2.0.5	Same	2.2.0.5	00:00:45	Pending
No	XJDI	0.1.4.1	Older	0.1.2.2	00:01:15	Pending
No	Gamma	0.0.2.3	Same	0.0.2.3	00:00:15	Pending
Yes	XDTM	7.3.0.68	Older	7.0.0.0	00:01:30	Success
No	Flow Switch	0.1.3.7	Newer	2.0.0.1	00:02:00	Pending
No	DynamX	0.0.1.26	Newer	0.0.1.28	00:00:30	Pending
Yes	PPP	0.4.0.33	Older	0.0.0.10	00:01:00	Success

Below the table is a 'Flash Update Progress' section with a green progress bar and three buttons: 'Cancel', 'Update', and 'Next'. At the bottom of the window is a navigation bar with buttons for 'Run Info', 'Firmware' (highlighted), 'Configs', 'Highside', 'Diagnostics', 'Report', and 'Run Menu (Run 1, Active)'. The status bar at the very bottom shows 'PCAN Idle' and 'Tools: 10'.

Tool Programming – Configuration Files

- Configuration files (configs) are similar to DTCs (PF) or Frames (D&M)
- Contains data frame list for survey, toolface logging, rotating and status frames
- Config files may be obtained through OSC and should only be updated through InTouch ticket
- Associated with datafile which controls WITS IDs, data point ranges and limits. Data file must match configs
- Save the Data File in the Data File folder on programming computer and decoding computer
 - \\C:\ExtremeEngineering\DataFile
- Save the Configurations in the Configuration folder on programming computer and decoding computer
 - \\C:\ExtremeEngineering\XDT\Configurations
 - \\C:\ExtremeEngineering\XEM\Configurations
 - \\C:\ExtremeEngineering\XPulse\Configurations



Tool Programming – Configuration Naming Convention

Example:

8-5-19 XDAG Cont ATF MUD XDT 4Hz-4c XP1Hz-2c CFG 2

- Safety Disabled means that pressure safety is disabled and the tool will transmit when vibrated, regardless of pressure
 - This configuration is utilized when the pressure sensor fails downhole
- 8-5-19 is the date the configuration was created
- XDAG shows that configs are set up for XDAG gamma/D&I
- Cont shows that config contains continuous Inc/Azi data
- ATF means that tool is set up for auto toolface based on last survey taken by tool
- MUD refers to flow switch vibrations settings
 - MUD drilling has low “flow off” vibration setting
 - AIR drilling has high “flow off” vibration setting
- 4Hz-4C is standard EM data rate for config
- XP1Hz-2C is standard MP data rate for config
- CFG 2 represents config number

Tool Programming – Configuration Download – Extreme Probes

- Select config folder path
 - Verify DynamX and Gamma configs are selected
- Select power setting on tool
 - Selection based on local best practice
 - If unsure, program with 5 watts and adjust via EM downlink downhole
- Select XDT tool mode
 - If programming in DT mode, it's recommended to start with MP mode for bank test work flow

The screenshot displays the 'EXTREME MEASUREMENT WHILE DRILLING' software interface. The main window is titled 'Download Configurations' and contains a 'SETTINGS' section with the following parameters:

- Config file folder path: C:\ExtremeEngineering\Configurations\XDT\Field\XDT_DynamX_Cont_ATF 15-10deg_GammaExt_MUD_November 4, 2018
- XDT power setting: 1 Watt
- XDT tool mode: EM Mode
- DDR Listening Freq/BitRate: 1.00 Hz, 1 bps
- Should erase flash: No
- Estimated time to erase: 49.9 min (total flash size is 19.3 MB)

Below the settings is a table titled 'CONFIGURATIONS - PLEASE CHOOSE THE ACTIVE CONFIGURATION FOR DIAGNOSTICS, HIGHSIDE AND ROLL TEST'.

ACTIVE	NUM	ANGLE	IDLE	CONFIGURATION FILE NAME
No	1	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_4H2c_1H2c_CFG_1.V13Cfg
Yes	2	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_2H2c_1.5H2c_CFG_2.V13Cfg
No	3	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_2H2c_0.75H2c_CFG_3.V13Cfg
No	4	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_1H2c_1.25H2c_CFG_4.V13Cfg
No	5	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_8H4c_2H2c_CFG_5.V13Cfg
No	6	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_6H3c_1H1c_CFG_6.V13Cfg
No	7	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_4H2c_1H2c_CFG_7.V13Cfg
No	8	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_12H6c_1.75H2c_CFG_8.V13Cfg

At the bottom of the interface, there are buttons for 'Refresh' and 'Next', and a navigation bar with tabs for 'Run Info', 'Firmware', 'Configs', 'Highside', 'Diagnostics', 'Report', and 'Run Menu (Run 1, Active)'. The status bar at the bottom left shows 'PCAN Idle' and 'Tools: 10'.

Tool Programming – Configuration Download – Extreme Probes (cont.)

- Select DDR listening freq/bit rate
 - 4Hz/4BPS most common in field
 - If other EM tools are used in the area, keep their uplink and downlink bit rates/frequencies in mind
- Choose flash erase option
 - If first run on probe or memory already dumped, set erase flash to yes
 - If reprogramming due to troubleshooting, do not erase flash
- Select desired config for run
 - Do not start run with safety disabled config

The screenshot displays the 'EXTREME MEASUREMENT WHILE DRILLING' software interface. The main window is titled 'Download Configurations' and contains a 'SETTINGS' section with the following fields:

- Config file folder path: C:\ExtremeEngineering\Configurations\XDT\Field\XDT_DynamX_Cont_ATF 15-10deg_GammaExt_MUD_November 4, 2018
- XDT power setting: 1 Watt
- XDT tool mode: EM Mode
- DDR Listening Freq/BitRate: 1.00 Hz, 1 bps
- Should erase flash: No
- Estimated time to erase: 49.9 min (total flash size is 19.3 MB)

Below the settings is a table titled 'CONFIGURATIONS - PLEASE CHOOSE THE ACTIVE CONFIGURATION FOR DIAGNOSTICS, HIGHSIDE AND ROLL TEST'.

ACTIVE	NUM	ANGLE	IDLE	CONFIGURATION FILE NAME
No	1	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_4H2c_1H2c_CFG_1.V13Cfg
Yes	2	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_2H2c_1.5H2c_CFG_2.V13Cfg
No	3	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_2H2c_0.75H2c_CFG_3.V13Cfg
No	4	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_1H2c_1.25H2c_CFG_4.V13Cfg
No	5	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_8H4c_2H2c_CFG_5.V13Cfg
No	6	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_6H3c_1H1c_CFG_6.V13Cfg
No	7	No		11-4-18_Safety Disabled_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_4H2c_1H2c_CFG_7.V13Cfg
No	8	No		11-4-18_XDT_DynamX_Cont_ATF 15-10_Gamma_MUD_12H6c_1.75H2c_CFG_8.V13Cfg

At the bottom of the interface, there are buttons for 'Refresh' and 'Next'. A navigation bar at the very bottom includes 'Run Info', 'Firmware', 'Configs', 'Highside', 'Diagnostics', 'Report', and 'Run Menu (Run 1, Active)'. The status bar shows 'PCAN Idle' and 'Tools: 10'.

Tool Programming – Configuration Download – xBolt Probes

- Ensure XDAG config files are selected
- Select nominal tool size for XDAG gamma correction
 - Be mindful of OD/IDs where gamma cartridge is located
 - In 675 flex collar, select 475 tool size if gamma is in flex portion of collar
- Crossover angle programmable in software instead of configuration

The screenshot displays the 'EXTREME MEASUREMENT WHILE DRILLING' software interface. The main window is titled 'Download Configurations' and contains a 'SETTINGS' section with the following parameters:

- Config file folder path: C:\ExtremeEngineering\Configurations\XDT
- XDT power setting: 0.5 Watt
- XDT tool mode: Pulse Mode
- Nominal tool size: 4.75 inch
- Crossover Angle Threshold: 3° to 5°
- DDR Listening Freq/BitRate: 1.00 Hz, 1 bps
- Should erase flash: Yes
- Estimated time to erase: 13.0 min (total flash size is 5.0 MB)




Below the settings is a table of configurations:

ACTIVE	NUM	ANGLE IDLE	CONFIGURATION FILE NAME
Yes	1	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma300_QPSK_EM4h2c_P1h2c_Config_1.V13Cfg
No	2	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma600_QPSK_EM6h3c_P1.5h2c_Config_2.V13Cfg
No	3	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma300_QPSK_EM4h4c_P0.75h2cNoAzi_Config_3.V13Cfg
No	4	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma300_QPSK_EM8h8c_P1h2c_Config_4.V13Cfg
No	5	No	4-12-19_SafetyDisabled_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma600_QPSK_EM4h2c_P2h2c_Config_5.V13Cfg
No	6	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma1200_QPSK_EM8h4c_P1.25h2c_Config_6.V13Cfg
No	7	No	4-12-19_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma300_QPSK_EM10h10c_P0.5h2c_Config_7.V13Cfg
No	8	No	4-12-19_SafetyDisabled_XDT_XDAG_XHOP_DynamX_Cont_ATF 5-3_PD1_Gamma300_QPSK_EM6h6c_P1h2cNoAzi_Config_8.V13Cfg

At the bottom of the window, there are navigation buttons: 'Run Info', 'Firmware', 'Configs' (highlighted in green), 'Highside', 'Diagnostics', 'Report', and 'Run Menu (Run 1, Not Active)'. The status bar at the bottom left shows 'PCAN Idle' and 'Tools: 0'.

Tool Programming – Highside

- Highside tool
- Check all SWIs once tasks complete
- Begin roll test, wait for calibration/survey then:
 - Roll to 90R, wait for survey
 - Roll to 180, wait for survey
 - Roll to 90L, wait for survey



$\Delta 90^\circ$

Tool Programming – Highside Diagnostics

- Confirm highside diagnostics
- All diagnostics should pass except DIP and MTOT
 - Verify DIP and MTOT delta limits not exceeded
 - If other magnetics are out of FAC, move tool away from magnetic interference (specifically jack stands) and redo roll
 - If any other measurements fail, investigate potential causes
 - Check FAC inputs in “Survey” tab

Highside

▼ AX	X-Axis accelerometer measurement stability	Pass
▼ AY	Y-Axis accelerometer measurement stability	Pass
▼ AZ	Z-Axis accelerometer measurement stability	Pass
▼ MX	X-axis magnetometer measurement stability	Pass
▼ MY	Y-axis magnetometer measurement stability	Pass
▼ MZ	Z-axis magnetometer measurement stability	Pass
▼ AZI	Azimuth measurement range	Pass
▼ INC	Inclination measurement range	Pass
▼ GTOT	Total Gravity Field measurement stability	Pass
▲ MTOT	Total Magnetic Field measurement stability	Failure
0°: 0.4681Ga Delta: 0.0014Ga Total magnetic field either changed too much during the roll test or failed FAC. Tool may have been moving during survey or magnetic interference is present nearby. Please check FAC values. Highside step can be repeated if tool movement is suspected.		
90°: 0.4677Ga Delta Lower Limit: 0.0000Ga		
180°: 0.4667Ga Delta Upper Limit: 0.0600Ga		
270°: 0.4680Ga FAC Lower Limit: 0.4700Ga		
Result: Failure FAC Upper Limit: 0.4760Ga		
▼ GTF	Toolface measurement range	Pass
▲ DIP	Dip angle measurement stability	Failure
0°: 57.5° Delta: 0.1° Measured dip angle either varied too much during the roll test or failed FAC. Tool may have been moving during survey or magnetic interference is present nearby. Please check FAC values. Highside step can be repeated if tool movement is suspected.		
90°: 57.5° Delta Lower Limit: 0.0°		
180°: 57.3° Delta Upper Limit: 0.9°		
270°: 57.4° FAC Lower Limit: 58.8°		
Result: Failure FAC Upper Limit: 59.7°		

Tool Programming – Pre Run Diagnostics

- Run diagnostics, all checks should pass
- Common failures
 - Temperature exceeding range on multiple nodes, normal during summer
 - Battery bus voltage and measure voltage failure, if showing ~17V, turn tool power off on XM4 and re-run diagnostics
- When diagnostics complete, generate pre-run report for OSC QC

The screenshot displays the 'EXTREME MEASUREMENT WHILE DRILLING' software interface. The main window shows a list of diagnostic checks, all of which have passed. The status bar at the top indicates 'Bad: 1 Good: 56 Pending: 0'. The sidebar on the right contains icons for various tools and components, including XDTM, PPP, XDT ClassD, DDR, Flow Switch, Battery A, Battery B, XJDI, DynamX, Gamma, and String XDT. The bottom of the interface features a 'Diagnostics Progress' bar, a 'Cancel' button, a 'Run All' button, and a 'Next' button. The bottom status bar shows 'PCAN [] Idle' and 'Tools: 11'.

Component	Check Name	Status
XDTM	Temperature Measured by Telemetry	Pass
XDTM	Total Amp Hours Remaining	Pass
XDTM	Battery Current Measured by Telemetry	Pass
XDTM	Configuration Number	Pass
XDTM	EM Telemetry Power Target	Pass
XDTM	Telemetry Safety Error Flag	Pass
PPP	Temperature Measured by PPP (Bore)	Pass
PPP	Pressure Measured by PPP (Bore)	Pass
DDR	DDR Listening Frequency (Hz)	Pass
DDR	DDR Listening Bit Rate (bps)	Pass
Flow Switch	Flow Status	Pass
Battery A	Configuration Number	Pass
Battery A	Measured Current	Pass
Battery A	Measured Voltage	Pass
Battery A	Amp Hours Remaining	Pass
Battery A	Bus Voltage	Pass
Battery A	Cell 1 Voltage	Pass
Battery A	Cell 2 Voltage	Pass
Battery A	Calibration Low Offset	Pass
Battery A	Calibration Low Coefficient	Pass
Battery A	Calibration High Offset	Pass
Battery A	Calibration High Coefficient	Pass
Battery A	Measured G_Total	Pass
Battery A	Battery Type	Pass
Battery B	Configuration Number	Pass
Battery B	Measured Current	Pass
Battery B	Measured Voltage	Pass

xBolt Tool Pre-Run Preparations

Bank Test



Bank Test – Mud Pulse Bank Test Preparation

- Install vibrator on tool
 - Preferably on 1.75” barrel
 - Away from connections
 - NOT on battery probes
 - Isolate barrel from vibrator with electrical tape
- Highside tool



Bank Test – Mud Pulse Bank Test


- Close tool setup window in XDirect
- Open XDT Pulser Bank Test
- Select datafile and programmed config
- Verify trace begins scrolling in XDT Pulser Bank Test receiver
- Plug in vibrator to begin bank test



Decode over CAN for MP bank test can lead to poor decode. Recommend to decode at 1BPS or less

Bank Test – Mud Pulse Bank Test (cont.)

- If DT:
 - Decode one full survey and toolface frame, verify all dpoints are reading normal values
 - EM Downlink to EM mode
- If MP Only:
 - Decode one full survey and toolface frame
 - Change inclination and azimuth by a minimum of 2°
 - Recycle flow to get second survey (turn vibrator off for 30 second and turn back on)
 - Roll toolface to 90R, 180 and 90L during bank test
 - Verify all dpoints are reading normal values




Decode over CAN for MP bank test can lead to poor decode. Recommend to decode at 1BPS or less


Bank Test – EM Bank Test Preparation

- Install bike pump with bore pressure test clamp and pressure up to ~150psi
- **Clamp XLR clamps above and below gap probe plastic sleeve**
 - For R Tool, connect above spring
 - For L Tool, connect on landing ring
 - For EM, connect to EM Fishing Head
 - For connection below gap, clamp to bow springs or jack stand that is touching tool
- Remove HHROTC and install/torque end termination




Bank Test – EM Bank Test

- Open XM4 Receiver 
- Select datafile and programmed config
- Verify trace begins scrolling in XM4 receiver
- Plug in vibrator to being bank test



Bank Test – EM Bank Test (cont.)

- Decode one full survey and toolface frame
- Change inclination and azimuth by a minimum of 2°
- Recycle flow to get second survey (turn vibrator off for 30 second and turn back on)
- Roll toolface to 90R, 180 and 90L during bank test
- Minimum of 2 EM downlinks should be sent during course of bank
- Verify all dpoints are reading normal values
- Ensure tool is in desired settings prior to P/U tool



Bank Test – Pre-Run Files

- Recommended pre-run deliverables
 - XDirect Pre-Job Report
 - XM4 decode logs from bank test
 - X-Pulse decode logs from bank test
 - EMDownlinkerLogFile
 - Local Pre-Run Requirements

The screenshot shows the 'PreRunQC_Lagun' application window. It contains a form with the following fields and values:

Run#	11	Prerun Complete	<input checked="" type="checkbox"/>
Hole Size	6.75		
MWD Tool	Lagun MP/EM	Sent on Time	<input checked="" type="checkbox"/>
DD Tool	PowerDrive Ori	Crew Info	<input checked="" type="checkbox"/>
Other Tools		InterACT Path	<input type="checkbox"/>
Program/Bank Test	Good		
DD BHA	Good		
EDI	Good		
DNInits	Good		
TFC	NA		
Downlinker File	Good		
Mud Report	Good		
Offset Calc	Good		
Gamma Gain	Good		
SHT	Good		

Comments

Submitted By: Sarah Almohsen
QC'd By: Sergio V.

While tripping in hole:
- Start streaming to InterACT
- Begin SWIs/Checklists

xBolt Tool Pre-Run Preparations

Equipment Checks and Preparation

Equipment Checks and Preparation – XDT Bore Pressure Port Protector

- Once bank test complete and approved by OSC, install bore pressure port protector into XDT
- “+” side of protector goes into tool
- Protects against wash and debris collection inside pressure port



(03XEM0048)



Equipment Checks and Preparation – Muleshoe Sleeve & R-Pulser

- Assemble the muleshoe sleeve
 - Verify orifice is proper selection for planned run flow rate
 - Inspect outer sleeve for damage and wear, replace external o-rings between runs
 - Inspect internal helix and key seat for wash




- Verify pulser o-rings installed correctly
 - Two #325 o-ring uphole
 - One #220 o-ring downhole

Muleshoe OD	Sleeve OD	Orifice OD	Orifice #	Jet Holes	Jet Hole ID	Max Flow	Med Flow	Min Flow	TFA (sq-in)
9 1/2" – 6 1/4"	3 3/4"	2.75"	10	8	0.375	1000	850	700	1.669
			9	8	0.348	900	750	600	1.546
			8	8	0.328	800	675	550	1.461
			7	6	0.348	700	575	450	1.356
			6	6	0.328	550	475	400	1.292
			5	5	0.339	500	425	350	1.053
			4	4	0.328	450	375	300	.939
4 3/4"	3 1/4"	2.50"	3	3	0.328	350	275	200	.855
			2	3	0.281	280	230	170	.780
			1	2 (flutes)	.390 (wide)	220	180	130	.681

Equipment Checks and Preparation – Gap Sub

- Complete electrical test on gap sub
 - Electrically isolate gap sub by putting on wooden pallet
 - Clean any dope off connections where clamps will be installed
 - Install clamps (22CABL0071) to box and pin end of gap sub and plug into XEM Gap Sub Tester (22XEM 0014)
 - For full procedure refer to ITC# [7024808](#)



Application	Resistance	Voltage (AC)
OBM	>3k Ohms	>4V(AC)
WBM	>60 Ohms	>0.5V (AC)
Failed	<60 Ohms	<0.5V (AC)

Equipment Checks and Preparation – Gap Sub (cont.)



- xBolt Uses Same Gap Subs as XEM
 - If using 8” Gap Sub, remove O-Rings from Sub ID Prior to picking up tools with gap sub o-ring pick (02JIGS5001)
 - If O-Rings are left in sub, o-rings could potentiall jam pulser, RSS or bit



(02JIGS5001)

Equipment Checks and Preparation – MOP Screens & PolyPacks

- Remove dummy screens from MOP
- Install MOP Screens into MOP prior to P/U BHA and torque to specification
 - 80 ft/lb – LF MOP Screen
 - 40 ft/lb – Mini-MOP Screen
- Install PolyPack/O-Ring to MOP
 - Mini MOP O-ring - 000-40836 (Alternate - 779-25854)
 - LF MOP Housing O-ring + Backup ring/Polypack - 777-94545 + 777-94548 (Alternate 000-35425)



Summary

- Learn how to assemble all xBolt tool string
- Know how to strap xBolt equipment for run
- Setup surface software for job
- Understand how to program and test tools
- Finalize equipment setup to pick up for run